

Inspection Photos  
Location Name: Lauridson  
Location: 317934



Photo 1  
Tank Battery Sign

Photo 2  
Tank Battery Sign

**Inspection Photos**  
**Location Name: Lauridson**  
**Location: 317934**



**Photo 3**  
**Partially buried vessel was present on 09/29/2018**

**Photo 4**  
**Another photo of partially buried vessel on 09/28/2018**

**Inspection Photos**  
**Location Name: Lauridson**  
**Location: 317934**



**Photo 5**  
**Partially buried vessel was present on 04/17/2019**

**Photo 6**  
**Partially buried vessel had been removed prior to 07/26/2019**

**Inspection Photos**  
**Location Name: Lauridson**  
**Location: 317934**



**Photo 7**

**Partially buried vessel had been removed prior to 07/26/2019**

**Photo 8**

**Partially buried vessel had been removed prior to 07/26/2019**

**Inspection Photos**  
**Location Name: Lauridson**  
**Location: 317934**



**Photo 9**  
**Weeds not being controlled**



**Photo 10**  
**Weeds not being controlled**

**Inspection Photos**  
**Location Name: Lauridson**  
**Location: 317934**



**Photo 11**  
**Trash**

**Photo 12**  
**Trash**