

Inspection Photos
Location Name: Reubel 1-4
Location ID: 320054



Pic 1

Pic 2 location proximity to houses

Inspection Photos
Location Name: Reubel 1-4
Location ID: 320054



Pic 3 mechanical issues/stained soil



Pic 4 door on ground for separator house

Inspection Photos
Location Name: Reubel 1-4
Location ID: 320054



Pic 5 unused riser not LOTO



Pic 6 gas meter run with no calibration/illegable

Inspection Photos
Location Name: Reubel 1-4
Location ID: 320054



Pic 7 gas meter run



Pic 8 separator

Inspection Photos
Location Name: Reubel 1-4
Location ID: 320054



Pic 9 Produced water vault/leak/spill



Pic 10

Inspection Photos
Location Name: Reubel 1-4
Location ID: 320054



Pic 11 venting wellhead equipment



Pic 12 venting wellhead equipment