

Inspection Photos

Location Name: Amoco Charter Schneider Tank Battery

Location: 444630



Photo 1

Open excavation with inadequate fencing and storm water BMPs.
Note pipes removed from excavation.



Photo 2

Open excavation with inadequate fencing

Inspection Photos

Location Name: Amoco Charter Schneider Tank Battery

Location: 444630



Photo 3

Pipes exposed within the open excavation



Photo 4

Pipes exposed within the open excavation

Inspection Photos

Location Name: Amoco Charter Schneider Tank Battery

Location: 444630



Photo 5
Open excavation



Photo 6
Open excavation. Note pipes removed from excavation .