

Inspection Photos
Operator: BP America
Location/API #: 067-08499
Date: 9-10-2019



Photo 1. View of the project area from the southeastern edge facing center.



Photo 2. View of the southern fill slope from the southeastern edge facing westward. Revegetation is progressing largely with intermediate wheatgrass.



Photo 3. View of Canada thistles (*Cirsium arvense*) within the outer revegetation area.



Photo 4. View of reference area vegetation facing northeastward. Vegetation is comprised of smooth brome and mixed perennial grasses.