

Inspection Photos
Location Name: Sheldon R. Sickler #4
Location ID: 318318



Photo #1 WH sign faded and has wrong operator information



Photo #2 PU weeds overgrown on loc.



Inspection Photos
Location Name: Sheldon R. Sickler #4
Location ID: 318318



Photo #3 Weeds growing along center of access rd.



Photo #4 WH, weeds growing around

Inspection Photos
Location Name: Sheldon R. Sickler #4
Location ID: 318318



Photo #5 Weeds growing around PU.



Photo #6 weeds growing around Electric panel area.