

Inspection Photos
Location Name: Dwight Gilbert Hanks B #2
Location ID: 317663



40.09272, -104.87937, 49
09/19/20

Photo #1 WH sign



40.09284, -104.87932, 49
09/19/20

Photo #2 PU

Inspection Photos
Location Name: Dwight Gilbert Hanks B #2
Location ID: 317663



Photo #3 Weeds growing along access rd.

Photo #4 stained soil around WH.

Inspection Photos
Location Name: Dwight Gilbert Hanks B #2
Location ID: 317663



Photo #5 Unused wiring in conduit and lying on ground.

Photo #6 unused electric box by electric transformers.