

**Inspection Photos**  
**Location Name: Vonasek #3**  
**Location ID: 336205**



**Photo #1 WH with PU removed.**



**Photo #2 PU set aside off loc.**

**Inspection Photos**  
**Location Name: Vonasek #3**  
**Location ID: 336205**



**Photo #3 Valve with possible leak. Stained soil under it.**