

**Inspection Photos**  
**Location Name: Great Western Sugar Pad**  
**Location ID: 332604**



Colorado Oil & Gas Conservation Commission  
40.33285, -104.89973, 1455.0m, 226°  
09/19/2019 11:04:35 AM

**Production facility**



Colorado Oil & Gas Conservation Commission  
40.3328, -104.89975, 1453.0m, 233°  
09/19/2019 11:05:10 AM

**Trash**



Inspection Photos  
Location Name: Great Western Sugar Pad  
Location ID: 332604



Trash



Trash



**Inspection Photos**  
**Location Name: Great Western Sugar Pad**  
**Location ID: 332604**



**Wellheads**



**Trash**



**Inspection Photos**  
**Location Name: Great Western Sugar Pad**  
**Location ID: 332604**



**Master valve and stained soil on Gold 9A-DU**



**Master valve and stained soil on Gold 11-9DU**