

Inspection Photos
Location Name: Binder 14-3
Location ID: 317859



Production facility



Wellhead

Inspection Photos
Location Name: Binder 14-3
Location ID: 317859



Trash



Trash

Inspection Photos
Location Name: Binder 14-3
Location ID: 317859



Trash



Produced water vault placard

Inspection Photos
Location Name: Binder 14-3
Location ID: 317859



DCP Midstream LOTO



DCP Midstream LOTO