

Piceance Creek Unit T87X
API: 05-103-10499 to 10503 and 10718 to 10721
Inspection: 679705511



39.90148, -108.25903, 6828.4ft, 94°
09/19/2019 02:57:37 PM

Photo 1. Well location.

Piceance Creek Unit T87X
API: 05-103-10499 to 10503 and 10718 to 10721
Inspection: 679705511



39.90078, -108.25788, 6823.2ft, 65°
09/19/2019 03:03:06 PM

Photo 2. Headers, separator, and tank.

Piceance Creek Unit T87X
API: 05-103-10499 to 10503 and 10718 to 10721
Inspection: 679705511



Photo 3. Fallen deadman.