

Inspection Photos

API: 05-071-06183

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/19/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-071-06183 | Date: 9/19/2019

Inspection Photos



Photo 1. Facing north at the location. There is an orange tape square at the location. There are numerous noxious weeds (Diffuse knapweed) throughout the site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06183 | Date: 9/19/2019

Inspection Photos



Photo 2. There is a small pile of knapweed that appears to have been cut. The knapweed has seed heads and must be cut, bagged, removed, and treated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06183 | Date: 9/19/2019

Inspection Photos




Photo 3. Facing northwest at the location. There are numerous Diffuse knapweed at the location. Knapweed was not found in adjacent undisturbed area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06183 | Date: 9/19/2019