

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/18/2019

Submitted Date:

09/18/2019

Document Number:

692602519

FIELD INSPECTION FORM

Loc ID 304576 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266241	WELL	PR	03/11/2003	GW	125-08718	SHANDY 41-11543	PR

General Comment:

Routine Inspection

Location			
Lease Road:			
Type	Access		
comment:	Trail through CRP and farmers yard		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to metal shed		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead and metal shed		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Electric panel		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator in metal shed		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:			Date:

Type: Gas Meter Run	# 1	
Comment:	Meter run in metal shed	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.644710,-102.140110
Comment:	Fiberglass water tank 50% buried				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 266241 Type: WELL API Number: 125-08718 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Pass					
Gravel	Pass	Compaction	Pass			

Comment: [Check dam on west side of location needs maintenance](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT