

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2019

Submitted Date:

09/19/2019

Document Number:

692602522**FIELD INSPECTION FORM**

Loc ID 321173 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 76175Name of Operator: SANDLIN OIL CORPAddress: 1580 LINCOLN ST SUITE 580City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Sandlin, Gary		SandlinOilCorporation@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259738	WELL	PR	04/01/2019	GW	009-06617	HEIRONIMUS 1	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Access to wellhead is farmed over		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sticker on tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by VGS		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Parkersburg unit		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter shed is 1800' SW of wellhead		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator on south side of wellhead		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Arrow gas engine		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		37.181830,-102.126820
Comment:	Tank is empty at time of inspection and stored neatly on location. Tank is disconnected and needs to be removed if not to be used in future production				

Corrective Action:		Date:	
Paint			
Condition			
Other (Content)			
Other (Capacity)	150bbbs		
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Maintenance
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	259738	Type:	WELL	API Number:	009-06617	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central meter run for (Heironymous 1 & Leach 1) 1800' SW								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT