

Inspection Photos
Location: 081-07006
Remediation # 7363
Inspection Date: 9/19/2019
Photos taken by Kris Neidel



Photo #1, 40.918905,-108.308160. looking Northeast, standing in land treatment area.



Inspection Photos
Location: 081-07006
Remediation # 7363
Inspection Date: 9/19/2019
Photos taken by Kris Neidel



Photo #2 40.918923,-108.308182. photo looking mostly north standing near the Sothern boundary of land treatment area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location: 081-07006
Remediation # 7363
Inspection Date: 9/19/2019
Photos taken by Kris Neidel



Photo #3 40.918943,-108.308113. Photo looking north in land treatment.



Inspection Photos
Location: 081-07006
Remediation # 7363
Inspection Date: 9/19/2019
Photos taken by Kris Neidel



Photo #4 40.915303,-108.322963. Antler staff collecting soil samples.



Inspection Photos
Location: 081-07006
Remediation # 7363
Inspection Date: 9/19/2019
Photos taken by Kris Neidel



Photo #5 40.915245,-108.322982. Soil sample collection.