

Agave Oil & Gas LLC, Haas 1-29  
039-06677

Inspection #688305723

9/5/2019

Routine Inspection

**Agave Oil & Gas, LLC.**

(817) 946-6860

**Haas 1-29**

NWSE S29-T7S-R62W, Elbert County

**AUTHORIZED PERSONNEL ONLY**

All personnel must check in with  
company representative.

**DANGER**

**NO  
SMOKING**

**DANGER**

**HIGH  
PRESSURE  
GAS**

**NOTICE**

**HARD HATS  
STEEL TOE SHOES  
& SAFETY GLASSES  
REQUIRED**

**CAUTION**

**HEARING  
PROTECTION  
REQUIRED IN  
DESIGNATED AREAS**

**IN CASE OF EMERGENCY CALL 911**

Directions: From CO-86 E & Comanche  
Creek Rd, travel North on Comanche  
Creek Rd 6.6 mi, turn West into location.

Colorado Oil and Gas Conservation Commission

39.40941, -104.35375, 6099.1ft, 200°

09/05/2019 04:35:24 PM





Colorado Oil and Gas Conservation Commission  
39.40931, -104.35456, 6105.6ft, 336°  
09/05/2019 04:37:34 PM





Colorado Oil and Gas Conservation Commission  
39.4092, -104.35434, 6102.4ft, 286°  
09/05/2019 04:36:59 PM





Colorado Oil and Gas Conservation Commission

39.4093, -104.35431, 6099.1ft, 172°

09/05/2019 04:36:17 PM