

Petroshare Corporation, Bruchez-UPRR 1
005-06531
Inspection #688305767
9/10/2019 Routine Inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



 PETROSHARE CORP.
EXPLORATION INC.

Bruchez-UPRR No. 1
NW SE Sec. 35-T4S-R63W
Arapahoe Co., Colorado
Critical  PETROSHARE CORP. Inc.
Operator No. 1017 (EMERGENCY CONTACT:
Emergency Phone No. (830) 303-500-1160 or 911

Colorado Oil and Gas Conservation Commission
39.65648, -104.40433, 5613.5ft, 223°
09/10/2019 10:47:34 AM



Colorado Oil and Gas Conservation Commission

39.65648, -104.4043, 5593.8ft, 34°

09/10/2019 10:48:10 AM



Colorado Oil and Gas Conservation Commission
39.65647, -104.40434, 5610.2ft, 270°
09/10/2019 10:47:38 AM



Colorado Oil and Gas Conservation Commission
39.65648, -104.40437, 5587.3ft, 214°
09/10/2019 10:47:49 AM



Bruchez -UPRR No. 1 Btry
NW SE Sec. 35-T4S-R63W
CR 137 & Cornell, 0.5 mi E. to Lenaview
Arapahoe Co., Colorado
Crin PETROSHARE | PETROSHARE CORP. Inc.
Operator No. 1017(EMERGENCY
CONTACT:
Emergency Phone No. (8 303-500-1160 8 or 911

Colorado Oil and Gas Conservation Commission
39.6563, -104.40345, 5590.6ft, 107°
09/10/2019 10:49:40 AM



Colorado Oil and Gas Conservation Commission
39.65641, -104.40371, 5593.8ft, 115°
09/10/2019 10:49:13 AM



Colorado Oil and Gas Conservation Commission
39.65642, -104.40374, 5597.1ft, 158°
.09/10/2019 10:49:10 AM