

Inspection Photos

Operator: Hilcorp Energy
Location/API #: 067-09370
Date: 9-16-2019



Photo 1. View of the project area from the western corner facing center.



Photo 2. View of the western fill slope facing northward. Reference area is comprised of open grass field such as what is show in blue circle.



Photo 3. View of wattles and pallet debris within the southeastern project area.