

USA PAN AM-B 16-4
API: 05-103-06444
Inspection: 679705521



Photo 1. Well location.

USA PAN AM-B 16-4
API: 05-103-06444
Inspection: 679705521

east



west

40.13742, -108.9602, 5772.8ft, 210°
09/20/2019 11:23:29 AM

Photo 2. Central battery.

USA PAN AM-B 16-4
API: 05-103-06444
Inspection: 679705521



Photo 3. East tank at central battery.



Photo 4. Enlargement of a tank 'hole'.

USA PAN AM-B 16-4
API: 05-103-06444
Inspection: 679705521



Photo 5. Open top tank.



Photo 6. Hole in berm 80' SW of pump jack.

USA PAN AM-B 16-4
API: 05-103-06444
Inspection: 679705521



Photo 7. Well head.



Photo 8. Casing valve.

USA PAN AM-B 16-4
API: 05-103-06444
Inspection: 679705521



Photo 9. Bag attached to casing valve.