

Inspection Photos

Loc#446582

Operator: URSA

Inspection Number: 692401353

Inspection Date: 8/19/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources




Photo#1:
Overview of Location to Southwest. Wildlife escape boards have been installed.

August 19, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa BMCD Loc#446582



Photo#2:
Ruderal/Debris weeds are established in areas.



Photo#3:
There is still concern at Southwest corner of site.

August 19, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa BMCD Loc#446582