

# *Inspection Photos*

*API#103-08671*


*Operator: Bayswater*

*Inspection Number: 692401232*

*Inspection Date: 7/31/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location; desirable vegetation is establishing

July 31, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Bayswater Equity Calup PA API#103-08671





Photo#2:  
Establishment of Halogeton, and Cheat grass.

July 31, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Bayswater Equity Calup PA API#103-08671