

Inspection Photos

API#103-09161

Operator: Bayswater

Inspection Number: 692401233

Inspection Date: 7/31/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location; desirable vegetation is establishing

July 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bayswater Emerald 279 PA API#103-09161



Photo#2:
Establishment of Halogeton on site.

July 31, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bayswater Emerald 279 PA API#103-09161



Photo#3:
There is evidence of vehicle tracking into Location.

July 31, 2019