

Inspection Photos
Location Name: G&D Hanks Production Facility
Location ID: 419217



Photo 1: Tank Battery Sign



Photo 2: Tank Battery



Inspection Photos
Location Name: G&D Hanks Production Facility
Location ID: 419217



Photo 3: BBLs faded on tank



Photo 4: BBLs faded on tank

Inspection Photos
Location Name: G&D Hanks Production Facility
Location ID: 419217



Photo 5: BBLs faded on tank



Photo 6: Unused Risers

Inspection Photos
Location Name: G&D Hanks Production Facility
Location ID: 419217



Photo 7: Unused Equipment in gas meter house