

Inspection Photos
Location Name: LDS A 9, 16, 20-8 Tank Battery
Facility ID: 466250



Photo #1 Tank Battery



Photo #2 Picture taken from the SE corner, Berm wall is Mangled up.



Inspection Photos
Location Name: LDS A 9, 16, 20-8 Tank Battery
Facility ID: 466250



**Photo #3 picture taken on the north side, Berm wall is
Mangled up.**