

Inspection Photos
Location Name: Leonard #33-21
Location ID: 318681



Photo #1 WH sign has wrong operator information




Photo #2 bradenhead



Inspection Photos
Location Name: Leonard #33-21
Location ID: 318681



Photo #3 weeds growing inside AG fencing



Photo #4 stained soil by WH



Inspection Photos
Location Name: Leonard #33-21
Location ID: 318681



Photo #5 unused unmarked riser no LOTO