

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/13/2019

Submitted Date:

09/17/2019

Document Number:

689703534

**FIELD INSPECTION FORM**Loc ID 335808 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name      | Phone | Email                                     | Comment                   |
|-------------------|-------|---|---------------------------|
| Kellerby, Shaun   |       | shaun.kellerby@state.co.us                |                           |
| Pesicka, Conor    |       | conor.pesicka@state.co.us                 |                           |
| , Caerus Piceance |       | COGCC.inspections@caerus<br>oilandgas.com | Piceance inspections only |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                 | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------------|-------------|
| 277667      | WELL | PR     | 11/06/2006  | GW         | 045-10744 | N.PARACHUTE WF09B<br>K23 596  | PR          |
| 277668      | WELL | PR     | 11/06/2006  | GW         | 045-10745 | N. PARACHUTE WF08D<br>K23 596 | PR          |
| 277669      | WELL | PR     | 07/18/2007  | GW         | 045-10746 | N. PARACHUTE WF08B<br>K23 596 | PR          |
| 277670      | WELL | PR     | 08/16/2007  | GW         | 045-10747 | N. PARACHUTE WF07D<br>K23 596 | PR          |
| 277671      | WELL | PR     | 09/03/2007  | GW         | 045-10748 | N. PARACHUTE WF10B<br>K23 596 | PR          |
| 277672      | WELL | PR     | 03/17/2006  | GW         | 045-10749 | N. PARACHUTE WF02D<br>K23 596 | PR          |
| 277673      | WELL | PR     | 11/20/2005  | GW         | 045-10750 | N. PARACHUTE WF15D<br>K23 596 | PR          |
| 277674      | WELL | PR     | 12/26/2005  | GW         | 045-10751 | N. PARACHUTE WF03D<br>K23 596 | PR          |

**General Comment:**

COGCC Inspection Report Summary

On Friday 09/13/2019 at approximately 1430 hrs), I, Inspector Mike Longworth, conducted a field inspection at CAERUS PICEANCE LLC N.PARACHUTE-65S96W 23NESW, at Location # 335808 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

Emergency Service Number or 911 not on battery sign.

Install sign to comply with Rule 210.b.

C.A. Date 10/17/2019

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location****Lease Road:**

|                    |        |       |  |
|--------------------|--------|-------|--|
| Type               | Access |       |  |
| comment:           |        |       |  |
| Corrective Action: |        | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |            |       |  |
|--------------------|------------|-------|--|
| Type               | BATTERY    |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |
| Type               | CONTAINERS |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |
| Type               | WELLHEAD   |       |  |
| Comment:           |            |       |  |
| Corrective Action: |            | Date: |  |

**Emergency Contact Number:**

|                    |  |                  |
|--------------------|--|------------------|
| Comment:           | Emergency Service Number or 911 not on battery sign. |                  |
| Corrective Action: | Install sign to comply with Rule 210.b.              | Date: 10/17/2019 |

**Good Housekeeping:**

|                    |       |       |  |
|--------------------|-------|-------|--|
| Type               | TRASH |       |  |
| Comment:           |       |       |  |
| Corrective Action: |       | Date: |  |

Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities  |                |       |      |             |           |         |    |               |    |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 277667         | Type: | WELL | API Number: | 045-10744 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 277668         | Type: | WELL | API Number: | 045-10745 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 277669         | Type: | WELL | API Number: | 045-10746 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 277670         | Type: | WELL | API Number: | 045-10747 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 277671         | Type: | WELL | API Number: | 045-10748 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 277672         | Type: | WELL | API Number: | 045-10749 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 277673         | Type: | WELL | API Number: | 045-10750 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 277674         | Type: | WELL | API Number: | 045-10751 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
|                  |                 | Ditches                 | Pass                  |  |                          |         |
| Berms            | Pass            |                         |                       |  |                          |         |
|                  |                 | Culverts                | Pass                  |  |                          |         |
|                  |                 |                         |                       | Material Handling And Spill Prevention | Pass                     |         |
| Compaction       | Pass            |                         |                       |  |                          |         |
|                  |                 | Compaction              | Pass                  |  |                          |         |
| Gravel           | Pass            |                         |                       |  |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 402178966    | INSPECTION SUBMITTED           | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939157">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939157</a> |
| 689703546    | Inspection 689703534 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939149">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939149</a> |