

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2019

Submitted Date:

09/17/2019

Document Number:

696300602

FIELD INSPECTION FORM

Loc ID 331106 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258556	WELL	SI	01/01/2019	GW	123-20160	LILLI FIELD UNIT 3-7	TA

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Good Housekeeping:

Type	TRASH		
Comment:	Trash inside the engine shed, see photo 2		
Corrective Action:	Comply with Rule 603.f	Date:	10/18/2019

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Panel and Barbed Wire		
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Bradenhead	# 1				
Comment:	Appears to be plumbed to surface				
Corrective Action:		Date:			
Type: Pump Jack	# 1				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 258556 Type: WELL API Number: 123-20160 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
Tank Battery has been decommissioned, all production equipment has been removed from location. Wellhead is TA'd. Trash in Engine Shed to be removed per Rule 603.f	petrie	09/17/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402178968	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939159
696300603	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4939154