

Construction and Stormwater Inspection

September 17, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 458940

Inspection Document #: 697500610

Weld County, CO

SWNE Section 26 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Chalk-Seeley Federal /7-26
Pad
Location ID: 458940



Photo 1. Photo taken from the entrance of the location, facing East. Photo illustrates culverts have been installed. The required permits were inside the mailbox. Operator shall install vehicle tracking device BMPs to ensure compliance with potential sediment discharges from operations, as a new access road has been constructed.



Photo 2. Photo taken from the entrance of the location, facing South. Photo illustrates the Operator has constructed a new access road (red-dashed lines) adjacent to an existing oil and gas access road. Operator indicated that the existing oil and gas access road would be reclaimed. Operator indicated the new access road was a County requirement.

Inspection Photos

Location Name: Chalk-Seeley Federal /7-26

Pad

Location ID: 458940



Photo 3. Photo taken from the western well pad location, facing North. Photo illustrates a ditch and berm BMP installed around the perimeter of location. Operator has only constructed the eastern portion of the location.



Photo 4. Photo taken from the western well pad location, facing South. See comments under Photo 3.

Inspection Photos

Location Name: Chalk-Seeley Federal /7-26

Pad

Location ID: 458940



Photo 5. Photo taken from the southwestern well pad location, facing East. See comments under Photo 3.



Photo 6. Photo taken from the southeastern well pad location, facing North. See comments under Photo 3.

Inspection Photos
Location Name: Chalk-Seeley Federal /7-26
Pad
Location ID: 458940



Photo 7. Photo taken from the eastern well pad location, facing North. Photo illustrates a topsoil stockpile (red-dashed lines) stored along the eastern perimeter.

Inspection Photos
Location Name: Chalk-Seeley Federal /7-26
Pad
Location ID: 458940



Photo 8. Photo taken from the northeastern well pad location, facing West. Photo illustrates a second topsoil stockpile stored along the northern well pad location.