

# Final Reclamation Inspection

September 17, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 319284

Inspection Document #: 697500612

Weld County, CO

SWNE Section 26 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: JONES, WALTER #1-26  
Location ID: 319284



**Photo 1.** Photo taken from the well/production facility location, facing South.  
Photo illustrates the Operator has failed to reclaim the location per Rule 1004.

Inspection Photos  
Location Name: JONES, WALTER #1-26  
Location ID: 319284



**Photo 2.** Photo taken from the well/production facility location, facing South. See comments under Photo 1.




Inspection Photos  
Location Name: JONES, WALTER #1-26  
Location ID: 319284



**Photo 3.** Photo taken from the well/production facility location, facing North. See comments under Photo 1.

Operator indicated this well/production facility location is planned to be used as part of the new Chalk Seeley access road. However, the Operator has only constructed a portion of the new access road- see Photo 4.

Inspection Photos  
Location Name: JONES, WALTER #1-26  
Location ID: 319284



**Photo 4.** Photo taken from the Chalk Seeley facility drawing. Photo illustrates the current disturbance from the Chalk Seeley construction (yellow= new access road that has been recently constructed for the Chalk Seeley location; fushia= eastern well pad has been recently constructed). As of 9/17/2019, the central and western location have not been constructed.