

# Final Reclamation Inspection

September 17, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 305727

Inspection Document #: 697500618

Weld County, CO

NENW Section 26 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: BUXMAN I #26-6  
Location ID: 305727



**Photo 1.** Photo taken from the well location entrance point, facing South. COGCC staff could not make a full assessment due to crop height and density, as the location was ~500' further south.

Inspection Photos  
Location Name: BUXMAN I #26-6  
Location ID: 305727



**Photo 2.** Photo taken from the well location entrance point, facing West. Photo illustrates the Operator has failed to remove the culvert. There is an access point for this crop field ~600 feet to the west of this point. This access point is no longer in use and was used for oil and gas operations. See Field Inspection Report Doc. #697500616 regarding the corrective action to remove the culvert.