

Inspection Photos
Location Name: BEARLY 24-29
API#: 05-071-08177
INSP. #: 695101400



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: BEARLY 24-29
API#: 05-071-08177
INSP. #: 695101400



PHOTO 3: APPEARS THAT PACKING WAS LEAKING ON WELLHEAD (NOT THERE IS NO LEAK AT TIME OF INSPECTION). IMPACTED AREA EXTENDS FROM WELLHEAD TO SOUTHWEST APP. 123'. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. CA DATE 9-25-19.



PHOTO 4: ANOTHER PATH EXTENDING FROM WELLHEAD WEST AND THEN SOUTH FOR APP. 93'.

Inspection Photos
Location Name: BEARLY 24-29
API#: 05-071-08177
INSP. #: 695101400



PHOTO 5: PHOTO SHOWING THAT THERE HAS BEEN OTHER EVENTS AS YOU CAN SEE THE WHITE CHALKY STAINING BEYOND THE CURRENT WET SOIL. WHITE CHALKY STAINING EXTENDS PAST CURRENT WET SOIL APP. 18'.