

Inspection Photos
Location Name: CECIL-66N64W /2NENE
Location #: 305248



Photo #1
Cecil 41-2 (05-123-22707) Wellsite
Shut-In | SI
Weeds
prior insp.




Photo #2
Cecil 41-2 Wellsite
Shut-In | SI
Weeds appear mitigated

Inspection Photos
Location Name: CECIL-66N64W /2NENE
Location #: 305248



Colorado Oil & Gas Conservation Commission
40.52241, -104.50879, 1432.0m, 237°
09/09/2019 04:14:32 PM

Photo #3
Cecil 41-2, 31-2 Battery
Shut-down | Inactive
prior insp.



Colorado Oil & Gas Conservation Commission
40.52244, -104.50878, 1448.0m, 243°
09/23/2019 03:41:45 PM

Photo #4
Cecil 41-2, 31-2 Battery
Shut-down | Inactive