

Inspection Photos Location #324349



Location



Inspection Photos Location #324349



39.39353, -107.73269, 2210.6m, 55°
08/22/2019 10:52:38 AM

Previous photo of tank missing label



39.39356, -107.73264, 2199.6m, 54°
09/24/2019 09:21:05 AM

Tank has been labeled



Inspection Photos Location #324349



Previous inspection photo of dead man



Dead man has been removed

