

Inspection Photos
Location Name: Colorado Federal #1
Location ID: 318901



Photo 1 – Pumping Unit – Unused Equipment, weeds, and trash

Photo 2 – Tank Battery, weeds actively growing in and out of berm. Tanks are unused equipment

Inspection Photos
Location Name: Colorado Federal #1
Location ID: 318901



Photo 3 – Weeds growing around Tank Battery berm



Photo 4 – Weeds at Separator, unused equipment

Inspection Photos
Location Name: Colorado Federal #1
Location ID: 318901



Photo 5 – Trash North West of Pumping Unit




Photo 6 – Debris and unused equipment inside the Engine Shed

Inspection Photos
Location Name: Colorado Federal #1
Location ID: 318901



Colorado Oil and Gas Conservation Commission
40.63084, -103.85129, 4694.1ft, 237°
09/19/2019 12:22:25

Photo 7 – Debris and unused equipment inside the Engine Shed



Colorado Oil and Gas Conservation Commission
40.63071, -103.85136, 4704.9ft, 6°
09/19/2019 11:06:45

Photo 8 – Open Well Bore – Please install Nightcap or Cut and Cap well.