

Inspection Photos
Location Name: Lundvall 18
API #: 05-123-13003



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Lundvall 18
API #: 05-123-13003



Photo 3: Tank Battery Sign



Photo 4: Location

Inspection Photos
Location Name: Lundvall 18
API #: 05-123-13003



Photo 5: Weeds in berm



Photo 6: Inadequate berm/Weeds in berm

Inspection Photos
Location Name: Lundvall 18
API #: 05-123-13003



Photo 7: No BBLs labeled