

**Inspection Photos**  
**Location Name: Reubel 1-3 Pit**  
**Location ID 114239**



**Photo 1 – Battery location sign**



**Photo 2 – Location photo; cement produced water vault on site**

**Inspection Photos**  
**Location Name: Reubel 1-3 Pit**  
**Location ID 114239**



**Photo 3 – Location photo**



**Photo 4 – Stained soil at crude oil tank access panel**



**Inspection Photos**  
**Location Name: Reubel 1-3 Pit**  
**Location ID 114239**



**Photo 5 – Stained soil at separator**




**Photo 6 – Stained soil at separator**

**Inspection Photos**  
**Location Name: Reubel 1-3 Pit**  
**Location ID 114239**



**Photo 7 – Wellhead location sign**



**Photo 8 – Stained soil at wellhead**

**Aerial Imagery**  
**Location Name: Reubel 1-3 Pit**  
**Location ID 114239**



**Photo 9 – 1993 aerial imagery**





**Aerial Imagery**  
**Location Name: Reubel 1-3 Pit**  
**Location ID 114239**



**Photo 10 – 2002 aerial imagery**

**Aerial Imagery**  
**Location Name: Reubel 1-3 Pit**  
**Location ID 114239**



**Photo 11 – 2018 aerial imagery**