

Inspection Photos  
Location Name: Reubel 1-4 Pit  
Location ID 114240



Photo 1 – Battery location sign



Photo 2 – Location photo; cement produced water vault on site. See Field Inspection No. 699500086 for corrective actions.


**Aerial Imagery**  
**Location Name: Reubel 1-4 Pit**  
**Location ID 114240**



**Photo 3 – 1993 aerial imagery**




**Aerial Imagery**  
**Location Name: Reubel 1-4 Pit**  
**Location ID 114240**



**Photo 4 – 2002 aerial imagery**

**Aerial Imagery**  
**Location Name: Reubel 1-4 Pit**  
**Location ID 114240**



**Photo 5 – 2018 aerial imagery**

