

**Inspection Photos**  
**Location Name: Abner Guthrie 2&3 Pit**  
**Facility ID 113811**



**Photo 1 – Tank Battery Sign**



**Photo 2 – Location photo**

**Inspection Photos**  
**Location Name: Abner Guthrie 2&3 Pit**  
**Facility ID 113811**



**Photo 3 – Location photo; fiberglass produced water tank on site**



**Photo 4 – Location photo**



**Aerial Imagery**  
**Location Name: Abner Guthrie 2&3 Pit**  
**Facility ID 113811**



**Photo 5 – 1993 aerial imagery**



**Aerial Imagery**  
**Location Name: Abner Guthrie 2&3 Pit**  
**Facility ID 113811**



**Photo 6 – 2002 aerial imagery**

**Aerial Imagery**  
**Location Name: Abner Guthrie 2&3 Pit**  
**Facility ID 113811**



**Photo 7 – 2006 aerial imagery**



**Aerial Imagery**  
**Location Name: Abner Guthrie 2&3 Pit**  
**Facility ID 113811**



**Photo 8 – 2008 aerial imagery**



**Aerial Imagery**  
**Location Name: Abner Guthrie 2&3 Pit**  
**Facility ID 113811**



**Photo 9 – 2018 aerial imagery**