

Inspection Photos
Location Name: Ocoma 31-26
Facility ID: 249614



Photo #1 Wellhead & Sign



Photo #2 broken stainless line that runs motor valve.

