

Inspection Photos
Location Name: Crystal-Hubbs 1
Location ID: 320166



Pic 1 wellhead no sign



Pic 2 wellhead no sign

Inspection Photos
Location Name: Crystal-Hubbs 1
Location ID: 320166



COLORADO OIL AND GAS CONSERVATION COMMISSION
39.95019, -104.42132, 5017.3ft, 325°
09/26/2019 11:59:16

Pic 3 venting wellhead



COLORADO OIL AND GAS CONSERVATION COMMISSION
39.94933, -104.42359, 5033.5ft, 323°
09/26/2019 12:03:30

Pic 4

Inspection Photos
Location Name: Crystal-Hubbs 1
Location ID: 320166



Pic 5 stained soil/mechanical issue



Pic 6 stained soil/mechanical issue