

Inspection Photos
Location Name: Gruwell 44-32
Location ID: 313299



Photo 1. Overview of location taken facing south.



Photo 2. Weeds in tank battery.



Inspection Photos
Location Name: Gruwell 44-32
Location ID: 313299



Photo 3. Trash and debris at wellhead.