

Inspection Photos
Location Name: Dechant State #3
Location ID: 333279



Colorado Oil & Gas Conservation C

Photo #1 WH sign



Colorado Oil & Gas Conservation C

Photo #2 WH/PU



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dechant State #3
Location ID: 333279



Photo #3 Stained soil appears to have been addressed



Photo #4 Stained soil appears to have been addressed

Inspection Photos
Location Name: Dechant State #3
Location ID: 333279



Photo #5 Mechanical issue appears to have been addressed