

Inspection Photos
Location Name: Federal Carbonera 1-2
Location ID: 322317
Inspection Date: September 11, 2019



Photo #1 – Aerial view of the location (GISOnline Maps).



Photo #2 – Location sign.

Inspection Photos

Location Name: Federal Carbonera 1-2

Location ID: 322317

Inspection Date: September 11, 2019



Photo #3 – View of the 2-inch flowline (Red circle).



Photo #4 – View of vegetation.

Inspection Photos
Location Name: Federal Carbonera 1-2
Location ID: 322317
Inspection Date: September 11, 2019



Photo #5 – View of vegetation.



Photo #6 – View of unused equipment.