

M.B. Larson A 2
API: 05-103-06332
Inspection: 679705601



Photo 1. Well head sign.



M.B. Larson A 2
API: 05-103-06332
Inspection: 679705601



Photo 2. Stained soil next to cellar.



Photo 3. Two unused pipes.