



00241346

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
Department of Natural Resources
Suite 380, Logan Tower Building
1580 Logan Street
Denver, Colorado 80203

A. T. SKAER
PO Box 22418
Den. 80222

Lease TETSELL B1 & B2
Field MT. HOPE EAST
County LOGAN
Location SESE 33-9N-53W

Gentlemen:

An inspection was made of the lease(s) shown above. The following conditions were observed to exist at the time of the inspection:

- Oil accumulation on the water in the retaining pit.
- Skim pit in need or repairs.
- Skim pit or tank should be constructed.
- No. I.D. number on tank.

Remarks: _____

The above condition(s) should be corrected immediately. Any surface accumulation of oil in the retaining pits must be cleaned off within ten (10) days after receipt of this notice (Rule 328), and a report submitted to this office within thirty (30) days after the work was accomplished, advising us of the date and manner in which the correction was made. Any person who fails to comply with this request is in violation of this Commission's Rules and Regulations and is subject to the penalties as provided for under 34-6-121 of the Oil and Gas Conservation Act.

William R. Smith
William R. Smith, Director

Rec
N

LEASE INSPECTION FORM

Operator A T Spaer Date May 30 1985
 Lease Name & No. Tetsell B1-B2 Field Mt Hope East
 Tank Battery No. 9N53 P 33 County Logan
 Location SESE 33-9N-53W
 Legal Description
 Type of Inspection Reg Pit
 Water Inflow _____ (Bbls. Per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)
 Type of Tank

SKIM TANK 10' dia - Steel ~~Sheet~~ Wire Cover - 100%
 Pit No. 1 40 x 40 - 50% Covered
1' Free
 Pit No. 2 oil blowing over side
 Pit No. 3 Skim - 10 x 10 - No Cover - 100%

ADDITIONAL PITS _____

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety
 Conditions, Etc.)

RECOMMENDED ACTION (If Required) Clean pit #1

INSPECTOR W B Biskup