

Inspection Photos
Operator: Kinder Morgan
Location/API #: 083-06645
Date: 9-18-2019



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing westward. Interim reclamation area and reference area is in a cultivated field that is not vegetated at this time.