

**Inspection Photos**  
**Operator: Kinder Morgan**  
**Location/API #: 083-06635**  
**Date: 9-18-2019**



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern edge facing northward. Revegetation is progressing, largely with western wheatgrass.



Photo 5. View of reference area comprised of dry grass field comprised of a mixture of native grasses such as western wheatgrass and non-native grasses such as crested wheatgrass.