

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/27/2019

Submitted Date:

09/27/2019

Document Number:

692602536**FIELD INSPECTION FORM**

Loc ID 304958 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277071	WELL	PR	08/31/2005	GW	125-09199	HEATH 22-27	PR

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by fiberglass shed		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign by VGS		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Metal panels around VGS and meter shed		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Separator	# 3		
Comment:	2-Vertical gas separators 50% buried by meter shed 1-Vertical gas separator in fiberglass shed		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:	Shared meter run for Heath 22-27 & 23-27	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.856890,-102.176780
Comment:	Fiberglass water tank 50% buried				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	210bbbs
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	277071	Type:	WELL	API Number:	125-09199	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Tubing valves closed. Casing valve to VGS is open. Central meter run for (Heath 22-27 AND Heath 23-27)								
Corrective Action:								Date:	

--	--	--	--	--	--	--	--	--	--

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Access has deep tracks and needs maintenance

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT