

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/27/2019

Submitted Date:

09/28/2019

Document Number:

696101346

FIELD INSPECTION FORM
 Loc ID 419804 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419801	WELL	SI	06/01/2017	OW	123-32358	BASHOR PC AA 17-18	TA
419802	WELL	SI	02/01/2017	OW	123-32359	BASHOR PC AA 17-02D	TA

General Comment:

This is a WELL & ABANDONED BATTERY Inspection.
 Well(s): 2 ; Temporarily Abandoned | TA.
 Battery: Abandoned & ALL equipment removed.

Abandoned Battery SE corner GPS coordinates: 40.490597, -104.460651
 Reclamation progressing.

Follow-up to Field Inspection Doc. #696100966 dated 05/29/2019.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	2: wellsites		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp: Unused equipment (Gas meter runs (2), riser, & signage) at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. Remove unused gas meter runs, riser, & signage. Comply w/ Rule 603.f. Corrective Action Date: 08/27/2019.</p> <p>This insp: * Unused equipment (Gas meter runs (2), riser, & signage) at Abandoned Battery site NOW appears removed. See photos #3, 4.</p>		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	2: wellsites. Iron panel.		
Corrective Action:			Date:
Equipment:			
Type: Emission Control Device	# 0		corrective date
Comment:	Battery: Abandoned & ALL equipment removed.		
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:	2: wellsites. Appears plumbed to surface.		
Corrective Action:			Date:

Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 0		
Comment:	Battery: Abandoned & ALL equipment removed.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 0		
Comment:	Battery: Abandoned & ALL equipment removed.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment:	Battery: Abandoned & ALL equipment removed.					
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				40.490597,-104.460651
Comment:	Battery: Abandoned & ALL equipment removed.				
Corrective Action:					

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 419801 Type: WELL API Number: 123-32358 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery has been abandoned.
Locked & Tag-out (LOTO). Orange Decommission tag present.
COGCC records indicate last prod: 05/2017.
SI/TA. MIT requirement waived per variance Doc #401474555. (NOBLE)

Corrective Action: Date: Facility ID: 419802 Type: WELL API Number: 123-32359 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery has been abandoned.
Locked & Tag-out (LOTO). Orange Decommission tag present.
COGCC records indicate last prod: 02/2015.
SI/TA. MIT requirement waived per variance Doc #401474555. (NOBLE)

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 09/27/2019 at approximately 14:35 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: BASHOR PC AA /17-18 Location ID: 419804 Well Names: Bashor PC AA 17-18, Bashor PC AA 17-02D API: 05-123-32358, 05-123-32359 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s): 1 ; Temporarily Abandoned TA. Battery: Abandoned & ALL equipment removed.</p> <p>Abandoned Battery SE corner GPS coordinates: 40.490597, -104.460651 Reclamation progressing.</p> <p>Follow-up to Field Inspection Doc. #696100966 dated 05/29/2019.</p> <p>During this inspection the following prior possible compliance issues appear to be addressed: 1.) Unused equipment (Gas meter runs (2), riser, & signage) at Abandoned Battery site. Refer to Rule 603.f for guidance when machinery required to remove equipment. Remove unused gas meter runs, riser, & signage. Comply w/ Rule 603.f. Corrective Action Date: 08/27/2019. * Unused equipment (Gas meter runs (2), riser, & signage) at Abandoned Battery site NOW appears removed. See photos #3, 4.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/28/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101348	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4949896