

Inspection Photos
Location Name: WILHITE-67N64W /30SESW
Location #: 306508



Photo #1
Wilhite 30-34 (05-123-24807) Wellsite
Shut-In | SI
Weeds
from prior insp.



Photo #2
Wilhite 30-34 Wellsite
Shut-In | SI
Weeds appear mitigated

Inspection Photos
Location Name: WILHITE-67N64W /30SESW
Location #: 306508



Photo #3
Wagner 30-32, Wilhite 30-34 Battery
Shut-down | Inactive
from prior insp.



Photo #4
Wagner 30-32, Wilhite 30-34 Battery
Shut-down | Inactive