

Inspection Photos
Location Name: PETTINGER-66N64W /2SESE
Location #: 305154



Photo #1
Pettinger 44-2 (05-123-22572) Wellsite
Producing | PR
Weeds
prior insp.



Photo #2
Pettinger 44-2 Wellsite
Producing | PR
Weeds appear mitigated

Inspection Photos
Location Name: PETTINGER-66N64W /2SESE
Location #: 305154



Photo #3
Pettinger 44-2, 43-2, 33-2, 34-2 Battery
Active
prior insp.



Photo #4
Pettinger 44-2, 43-2, 33-2, 34-2 Battery
Active